### Work Order ID 61009

August 4, 2010 8:55:47 AM

Quality Control



Page 1

D4149-1 Accept Item ID: Setup Start **Revision ID:** Stop Crosstube Lug Plate, Aft Item Name: **Start Qty: 10.00 Start Date:** 8/04/10 **Cust Item ID:** Required Date: 8/11/10 Req'd Qty: 10.00 **Customer:** Reference: Run Start Date: // Tooling: Process Plan: Approvals: Date: Stop Date: SPC (Y/N): Date: Sequence ID/ Operation Reject Tool ID Tool # Plan Reject Set Up/ Accept Insp. Run Hours Work Center ID Description Code Qty Qty Number Stamp **Draw Nbr Revision Nbr** D4149 В 100 0.00 15 10-8-9 0.00 Waterjet Memo FLOW CNC Waterjet Cut as per dwg D4149 Prog Rev:\_\_ 178 304 Dwg Rev: Deburr as required 110 QC2- Inspect parts off machine FAI/FAIB 0.00 B10-9-4

0.00

Memo

D	а	rt	Α	e	O	S	p	а	C	е	L	td	

W/O:			W	ORK ORDER CHANG	SES					,
DATE	STEP	PRO	OCEDURE CH	IANGE	ı	Зу	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
									·	
						i		:		
Part No	•	PAR #:	Fault Ca	tegory:	_ NCR:	Yes I	lo DQA	-	_ Date: _	
	R	esolution:	Disposit	ion:	QA: N	I/C Clo	sed:		Date: _	
NCR:			PROCEDURE CHANGE  By Date Qty Approval Chief Eng / Prod Mgr  PAR #: Fault Category: NCR: Yes No DQA Date:  Disposition: QA: N/C Closed: Date:  WORK ORDER NON-CONFORMANCE (NCR)  iption of NC Corrective Action Section B							
DATE	STEP	Description of NC	Initial				verifica			Approvai
	0.2.	Section A			'		Section	С	Chief Eng	QC Inspector
						,				
			i I							
								1		
										1

#### Work Order ID 61009

August 4, 2010 8:55:47 AM



Page 2

Item ID:

D4149-1

Accept

Setup Start



**Revision ID:** 

Item Name:

Required Date: 8/11/10

Crosstube Lug Plate, Aft

**Start Date:** 

8/04/10

QC:

**Start Qty: 10.00** 

Req'd Qty: 10.00

**Cust Item ID:** 

**Customer:** 

Tool ID

Reference:

Approvals:

Process Plan:

Date:

Tooling: SPC (Y/N): Date:

Date:

Run

Start

Stop

Stop



Sequence ID/

Work Center ID

120

Quality Control

Operation Description

QC8- Inspect parts - second check

Date:

Memo

Set Up/ **Run Hours** 

Tool # Plan Code

Accept Qty

Reject **Qty** 

Reject Number

Insp. Stamp

150

Packaging

Memo

0.00

0.00

Packaging

160

Quality Control

QC21- Final Inspection - Work Order Release

Identify as per dwg & Stock Location:

Memo

0.00

0.00

W/O:		WORK ORDER CHAN					
DATE	STEP	PROCEDURE CHANGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
ાગેકોજ	170	Took aby +1 For ac inspection template	8	roloslog	41		50 10102/08

Part No:	PAR #:	Fault Category:	NCR: Yes No DQA	Date:
Resolutio	n:	Disposition:	QA: N/C Closed:	Date:

NCR:	·		WORK ORDER NON-CONFORMANCE (NCR)						
		Description of NC	•	Corrective Action Section B		Verificatio	n Approval	Approval	
DATE	STEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Section C		Approval QC Inspector	
	:		·						
				,					
		<u>.</u>							
					:	. }			

### **Picklist Print**

August 4, 2010 8:55:52 AM

Work Order ID: 61009

Parent Item: D4149-1

Parent Item Name: Crosstube Lug Plate, Aft



**Start Date:** 8/04/10

Required Date: 8/11/10

Page 1

**Start Qty:** 10.00

Required Qty: 10.00

**Comments:** 

IPP Rev:A 10.06.24 new issue DD verf:EC□

Component Item ID/ Item Name	Replacement Item ID	Mfg/ Purch	Bin Item	Primary Location	Last Location	Route Seq ID	Unit of Measure	Qty on Hand	Qty per Kit	Total Qty	Qty Issued	Date Issued	Status
M304S11GA		Purchased	No			100	sf	91.2982	0.1355	1.426316	1.5 1810-	9-8	
50 N 510 0.125 SHEET				<u>Location</u> MAT	114488 114799	<b>Loc Q</b> 91.2 1.5 89.7	982 5259	Loc Code		4799	(		

W/O:			W	ORK ORDER CHANG	ES					,
DATE	STEP	PRO	CEDURE CH	ANGE	Ву	,	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
			, 0.4.	<u></u>					1 100 Mgi	
						_			••	
										: : !
Part No	•	PAR #:	Fault Cat	egory:	_ NCR: Y	es N	o DQA:		_ Date: _	
	R	esolution:	Dispositi	on:	_ QA: N/0	Clos	sed:	ļ	Date:	
NCR:		V	VORK ORI	DER NON-CONFORM	ANCE (N	CR)				
DATE	STEP	Description of NC	Initial	<del></del>	tion B	gn &	Verifica		Approval	Approval
		Section A	Chief Eng	Action Description Chief Eng		ate	Section	<u>с</u>	Chief Eng	QC Inspector
			3							
								1		
								1		
								1		
,										

DART AEROSPACE LTD	Work Order:	
Description: CROSSTUBE LUG PLATE, AFT	Part Number: 4149-1	
Inspection Dwg: Du149-1 Rev: B	Page 1 of	1


# FIRST ARTICLE INSPECTION CHECKLIST

	X	First Article	. []	Prototype
--	---	---------------	------	-----------

ļ	rawing nension	Tolerance	Actual Dimension	Accept	Reject	Method of Inspection	Comn	nents
Ø	PCI.	100- 700 +	,131	*		VBOD		-
ø	,191	7.005001	. 192	0		V		
d	257	1.006 - 001	. >44	X		V		
Ø	.38	+ .606001	,379	×		V		
4	,310	11- 1010	311	*		V		
	.386	1/2 -010	.380	➣		V		
	750	1/2 .010	1750	ঠ		V		
	469	4/ -010	,47\	<b>&amp;</b>		V		
	3.50	T, ,530	3.200	8		V		
	.65	7/2 .330	,653	P.	<b></b>	V		
	,63	7L .030	PG3.	Ж		V		
	5.46	41 .030	5.460	8		V		
	3.80	4- 030	3.801	8		V		
	2,13	1/- 030	2.131	*		V		
	1.3:13	1/010-	-1.313	*		V		
	.375	4010	313	*		V		
	) <del>(</del> ) ( ) ( )	1/010	.625	*		V		· .
	1,175	7 .010	1.173	*		V		
	630	الله الله	754	*		٧		
	1.588	7/010	1.589	*		V		9,
	1.587	T010	1.597	*		V		
	1.781	4 .010	760	*		V		
	1.55	430	1.555			V		
	1192	OIO	119	7		_V		A1/A
Mea	asured by:	图	Audited by:	<del> </del>		Prototype A	pproval: Date:	N/A N/A
			1	1 / /		1	LISTP"	130/7

Date: N/A 10-8-9 Date:

				Revised by	Approved
Ī	Rev	Date	Change	KJ/JLM	
Ì	A		New Issue	Korocar	
]		<u> </u>			



ITEM DESCRIPTION D4149-041 AFT X-TUBE LUG ASSY X-TUBE LUG MOUNTING LUG AFT X-TUBE LUG PLATE SPACER D3910-1 D4091-1 D4149-1 D4149-3 1 D4149-5 EYEBOLT STUD AN3C12A AN4C13A MS20615-4M18 RIVET 9 (4 MS21043-3 NUT MS21043-4 NUT NAS1149C0332R WASHER 12 | 2 NAS1149C0432R WASHER


SHOP COUN WCONTROLLED COPY UNCURING AMENDMENT WITHOUT NOTICE

8	ADDED D7-2): R EACH A WASHE REPLACE	D4149-5 (SHT REPLACED QT' N3C12A, MS2 R (ZN D3-1, C CES Ø0.129.3	MS20615-4M20 (ZN D3-1 & B7-2); 5); D4149-5 WAS D3909-5 (ZN D3-1 & Y(3) MS20615-4M18 W1TH Q1Y(2) 1043-3 AND Q1Y(4) NAS1149C0332R -7-1, B7-2 & B3-2); Ø0.191 2 PL PL (ZN D8-3);	мв	10.07.05			
Α	NEWIS	SUE		MB	10.06.18			
REV.			DESCRIPTION	BY	DATE			
DESIG	DESIGN		DART AEROSPACE LTD					
DRAW	7		HAWKESBURY, ONTARIO		. —			
CHECK	ED	a a	DRAWING NO.		REV. B			
MFG. A	PPR.	_Q//	D4149		SHEET 1 OF 5			
APPRO	VED	140	TITLE		SCALE			
DE APP	PR.	_#	AFT X-TUBE LUG AS:	SY	NTS			
DATE	10.0	7.05	THE COCUMENT IS PRIVATE AND CONTENTIAL AND IS SUPPLIED ON THE CAPACITE CONTINUE AND					

D


## **Dart Aerospace Ltd**

W/O:			VV	ORK ORDER CHANGI	=5				
DATE STEP		PROCEDURE CHANGE			Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
								}	
Part No	•	PAR #:	Fault Cat	egory:	NCR: Ye	s No <b>DQA</b>	:	_ Date: _	_
	R	esolution:	Dispositi	on:	QA: N/C	Closed:		Date: _	<del> </del>
NCR:			WORK OR	DER NON-CONFORMA	NCE (NC	R)			
DATE	STED Description of NC		Corrective Action Sect			Verificat		Approval	Approval
DATE	STEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sigr Da	N& Section		Chief Eng	QC Inspector
			,						



Dart	<b>Aeros</b>	pace	Ltd
------	--------------	------	-----

W/O:			W	ORK ORDER CHA	NGES					
DATE STEP		PROCEDURE CHANGE				Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
				,						
Part No:			Fault Category:					i i		
	Re	esolution:	_ Disposit	ion:	QA	: N/C Cle	osed:		Date: _	·
NCR:		W	ORK OR	DER NON-CONFOR	RMANCE	(NCR	)			
DATE	STEP Description of NC		Corrective Action Section			/ Verificat			Approval	
DAIL	SIEP	Section A	Initial Chief Eng	Action Description Chief Eng	on	Sign & Date	Section		Chief Eng	QC Inspector
			:							
		•								
					Alexandrian de la companya de la com					
			1							
					·					




	Dá	art	Ae	ros	pac	e L	.td
--	----	-----	----	-----	-----	-----	-----

W/O:			W	ORK ORDER CH	ANGES					,
DATE STEP		PROCEDURE CHANGE				Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
									1 Tod Wgi	
	<u> </u>									
Part No	:	PAR #:	Fault Ca	tegory:	NC	R: Yes	No <b>DQA</b> :	<b> </b>	_ Date: _	<del></del>
	R	esolution:	Disposit	ion:	QA	N/C Clo	osed:		Date: _	
NCR:		\	WORK OR	DER NON-CONFO	PRMANCE	(NCR	)			
DATE	STEP	Description of NC			Section B			tion	Approval	Approval
DAIL	SIEP	Section A	Initial Chief Eng	Action Descrip Chief Eng	otion	Sign & Date	Section	¹ <b>¢</b>	Chief Eng	QC Inspector
								1.		

Ø0.38 Ø0.129 3 PL 4 PL 0 0.63 1.588 3.80 2.43 1.587 0.63 0.75 0.313 R0.38 - 0.735<sup>+0.000</sup> 0.375 -0.750 **D4149-3 SPACER** NOTES:
1) MATERIAL: 303/304/316 STAINLESS STEEL BAR PER ASTM A276 OR A582 REF DART SPEC MS304B OR MS303B
2) FINISH: NONE
3) TOLERANCES ARE PER DART QSI 018 UNLESS OTHERWISE NOTED 4) UNITS: INCHES UNLESS OTHERWISE NOTED 5) BREAK ALL SHARP EDGES: 0.005 TO 0.010 MAX 6) IDENTIFICATION: NONE 7) WEIGHT: 0.47 lbs DESIGN **DART AEROSPACE LTD** DRAWN HAWKESBURY, ONTARIO, CANADA CHECKED DRAWING NO. REV. B D4149 MFG. APPR. SHEET 4 OF 5 APPROVED TITLE SCALE AFT X-TUBE LUG ASSY DE APPR. DATE 10.07.05 COPYRIGHT @ 2010 BY DART AEROSPACE LTD

Dart	Aer	ospa	ce L	.td

	-									
W/O:	-		W	ORK ORDER CHANG	GES					<del>,</del>
DATE	STEP	PRO	OCEDURE CHA	ANGE		Ву	Date	પ્રેty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
				•						
										! :
								<u> </u>		
Part No	•	PAR #:	Fault Cate	egory:	NCR	l: Yes I	No DQA:		_ Date: _	
	Re	esolution:	Disposition	on:	QA:	N/C Clo	sed:		Date: _	
NCR:		,	WORK ORD	ER NON-CONFORM	IANCE	(NCR	)			
DATE	STED Description of NC		Corrective Action Section			VARITICS		tion	Approval	Approval
DATE	STEP	Section A	Initial Chief Eng	Action Description Chief Eng		Sign & Date	Section		Chief Eng	QC Inspector
									;	
						-				
								1		
									£	
	1 1		1		I		1		1	1



## Dart Aerospace Ltd

									٠.
W/O:			WC	RK ORDER CHANGES	3				
DATE	STEP	PRO	OCEDURE CHAI	NGE	Ву	Date Q	у	Approval Chief Eng / Prod Mgr	Approva QC Inspector
				·				·	
B1-200-		,							
Part No:		PAR #:	Fault Cate	gory:	NCR: Yes	No <b>DQA:</b> _		_ Date: _	
Resolution:			Disposition	QA: N/C Cld	osed:	Date:			
NCR:			WORK ORDER NON-CONFORMANC			)			
DATE	STEP Description of NC Section A		Initial Chief Eng	Corrective Action Section Action Description Chief Eng	Sign & Verification Section			Approval Chief Eng	Approval QC Inspecto
			Office Eng	Office Ling	Date				
		10.000							
		- Al-Pair Pair							
			1 1		1	1			1